



USA Installation

- Slide carriage ① to end of rail and remove lubrication nipple ② from end piece.
- Screw the lubrication nipple ④ supplied in the delivery into the lubrication adapter plate BPLE ③ and close off the open bore with the screw ⑤ provided.
- Place the lubrication adapter plate ③ in front of the standard wiper ⑥ and bolt it on using parts ⑦, ⑧.

! Only the bolt ⑦ supplied in the delivery should be used.

If a rail is to be equipped with more than one carriage, a guideway piece should be used for mounting purposes if possible.



ⓓ Montage

- Führungswagen ① an Schienenende fahren und Schmiernippel ② aus Kopfstück entfernen.
- In Schmieradapterplatte BPLE ③ mitgelieferten Schmiernippel ④ schrauben, offene Bohrung mit beiliegender Schraube ⑤ verschließen.
- Schmieradapterplatte ③ vor Standardabstreifer ⑥ setzen und anschrauben ⑦, ⑧.



Nur mitgelieferte Schraube ⑦ verwenden!
Werden mehrere Wagen auf einer Schiene ausgerüstet, möglichst Montageschiene verwenden.

